



IDC5
SOFTWARE
UPDATE

CAR 76.5.0



January 2024

IDC5 CAR 76.5.0

The **IDC5 CAR 76.5.0** software update includes, once again, a large number of developments, the best of TEXA's multi-brand diagnosis dedicated to cars and light commercial vehicles. Using IDC5 CAR during your daily workshop activities means having an avant-garde solution, rich in new diagnostic possibilities, special functions and technical information that are essential for completing even the most complex workshop operations professionally and with full customer satisfaction.

IDC5 CAR 76.5.0 includes the update of as many as 37 makes. The work of TEXA's technical developers also led to further increasing the coverage of the ADAS, electric and hybrid vehicles, interactive "DASHBOARD" screens and wiring diagrams.

IDC5 CAR 76.5.0 is characterised by over 2600 new possible selections for the major makes on the market worldwide, among which: **ABARTH, ACURA, ALFA ROMEO, ASTON MARTIN, AUDI, BENTLEY, BMW, BUICK, BYD, CADILLAC, CHERY, CHEVROLET, CHRYSLER, CITROËN, CUPRA, DACIA, DAIHATSU, DATSUN, DODGE, DR, DS, EVO, FERRARI, FIAT, FISKER, FORD, GENESIS, GMC, HOLDEN, HONDA, HUMMER, HYUNDAI, INEOS, INFINITI, ISUZU, JAGUAR, JEEP, KG MOBILITY, KIA, LADA, LANCIA, LAND ROVER, LAMBORGHINI, LDV, LEXUS, LINCOLN, LYNK & CO, MAXUS, MAYBACH, MASERATI, MAZDA, MCLAREN, MERCEDES-BENZ, MERCURY FORD, MG, MINI, MITSUBISHI, NISSAN, OPEL, PEUGEOT, POLESTAR, PONTIAC, PORSCHE, RAVON, RENAULT, RENAULT SAMSUNG, ROEWE, ROLLS-ROYCE, SAAB, SATURN, SCION, SEAT, SKODA, SMART, SSANGYONG, SUBARU, SUZUKI, TATA, TESLA, TOYOTA, TROLLER, UAZ, VENUZIA, VOLKSWAGEN, VOLVO.**

To learn more about the extraordinary coverage made available by TEXA, visit the website:

www.texa.com/coverage

LATEST IDC5 CAR VERSION UPDATE

In the "Latest version application list" section users can find the updates related to the diagnostic coverage available in the IDC5 CAR software (Image 1).




Image 1 - News section in IDC5.

NOTE: For further information see our website WWW.TEXA.COM in the DIAGNOSTIC COVERAGE section.

NEW FEATURES INCLUDED IN THE IDC5 CAR 76.5.0 VERSION**DIAGNOSIS****CAR****ACURA**

A new diagnosis of the GEAR SELECTOR LEVER system has been developed for the models:

- CDX [16>]
- ILX [13>22] (DE)
- Integra [23>] (DE)
- MDX [14>20] (YD)
- MDX [21>] (YE)
- TLX [14>20] (UB)

BMW

A new diagnosis of the SERVICE WARNING LIGHT system has been developed for the models:

- 1 [19>] (F40)
- 2 [21>] (G42)
- 2 [21>] (U06) Active Tourer
- 2 [23>] (G87)
- 4 [20>] (G22) Coupé
- 4 [21>] (G26) Gran Coupé
- 4 [21>] (G82) Coupé
- 4 [21>] (G83) Cabrio
- 7 [22>] (G70)
- i3 [13>22] (I01)
- i7 [22>] (G70)
- iX [21>] (I20)
- X1 [22>] (U11)
- X2 [18>] (F39)
- X3 [18>] (G01)
- X4 [18>] (G02)
- X5 [18>] (G05)
- X6 [19>] (G06)
- X7 [19>] (G07)
- Z4 [19>] (G29)



CAR 76.5.0



BYD

A new diagnosis of the DC/DC CONVERTER system has been developed for the models:

- Atto 3 [22>]
- Dolphin [21>]
- Yuan Plus [22>]

A new diagnosis of the BATTERY CHARGER CONTROL MODULE system has been developed for the models:

- Atto 3 [22>]
- Dolphin [21>]

A new diagnostic system has been developed for the model Song Plus [20>]:

- ABS
- AIRBAG
- POWER STEERING
- INSTRUMENTATION

A new diagnostic system has been developed for the model Song Pro [19>]:

- ABS
- AIRBAG
- POWER STEERING
- INSTRUMENTATION

CADILLAC

A new diagnosis of the AUTOMATIC TRANSMISSION system has been developed for the models:

- CT4 [20>]
- Escalade [21>]
- Escalade ESV [21>]
- CT5 [20>]

A new diagnosis of the DIFFERENTIAL LOCK ELECTRONICS system has been developed for the models:

- Escalade [21>]
- Escalade ESV [21>]
- CT4 [20>]
- CT5 [20>]

A new diagnostic system has been developed for the model Lyriq [23>]:

- EXTERNAL LAMP CONTROL UNIT

CHEVROLET

A new diagnostic system has been developed for the model Colorado [23>]:

- EXTERNAL LAMP CONTROL UNIT



CAR 76.5.0



A new diagnosis of the AUTOMATIC TRANSMISSION system has been developed for the models:

- Silverado 1500 [22>] Facelift
- Suburban [21>]
- Tahoe [21>]

A new diagnosis of the DIFFERENTIAL LOCK ELECTRONICS system has been developed for the models:

- Suburban [21>]
- Tahoe [21>]

DR

A new diagnosis of the SERVICE WARNING LIGHT system has been developed for the models:

- DR5.0 [20>]
- DR6 [17>20]
- Zero [15>]

EVO

A new diagnostic system has been developed for the model EVO 5 [20>22]:

- SERVICE WARNING LIGHT

FIAT

A new diagnostic system has been developed for the model 600e [23>] (364):

- AIRBAG
- GEAR SELECTOR LEVER

FORD

A new diagnostic system has been developed for the model F-Series Super Duty [11>16] (P473):

- ABS
- AIRBAG
- INJECTION SYSTEM INTEGRATION MODULE
- PETROL INJECTION
- DIESEL INJECTION
- AUTOMATIC TRANSMISSION
- PARK ASSIST
- BODY COMPUTER
- STEERING COLUMN SWITCH UNIT
- TYRE PRESSURE
- A/C

A new diagnosis of the TELEMATIC CONTROL UNIT system has been developed for the models:

- Figo [15>18] (B562)
- Figo Aspire [15>18] (B562)
- Ka [15>18] (B562)



CAR 76.5.0



- Ka [15>18] (B562)

A new diagnostic system has been developed for the model Territory [18>22] (CX743):

- ABS
- GATEWAY
- PETROL INJECTION
- PARK ASSIST
- BODY COMPUTER
- TYRE PRESSURE
- INSTRUMENTATION
- RADAR

GENESIS

A new diagnostic system has been developed for the model G80 [17>20] (DH):

- SPIA SERVIZIO

GMC

A new diagnosis of the EXTERNAL LAMP CONTROL UNIT system has been developed for the models:

- Canyon [23>]

A new diagnosis of the AUTOMATIC TRANSMISSION system has been developed for the models:

- Sierra 1500 [22>] Facelift
- Yukon [21>]
- Yukon XL [21>]

A new diagnosis of the DIFFERENTIAL LOCK ELECTRONICS system has been developed for the models:

- Sierra 1500 [22>] Facelift
- Yukon [21>]
- Yukon XL [21>]

HONDA

A new diagnosis of the GEAR SELECTOR LEVER system has been developed for the models:

- Accord IX [13>17] (CT/CR) Sedan
- Accord X [18>22] (CV) Sedan
- Accord XI [23>] (CY) Sedan
- Breeze [19>] (RY)
- City VII [19>]
- City VI [13>20]
- Civic X [16>21] (FC/FK) Hatchback
- Civic X [16>21] (FC/FK) Sedan
- Civic XI [21>] (FE) Sedan
- Civic XI [21>] (FL) Hatchback



CAR 76.5.0



- Crider [18>]
- CR-V [17>22] (RW/RT)
- CR-V [23>] (RS)
- HR-V [21>] (RV)
- HR-V [23>] (RZ)
- ZR-V [23>] (RZ)

HYUNDAI

A new diagnostic system has been developed for the model Staria [22>] (US4):

- GEAR SELECTOR LEVER

ISUZU

A new diagnostic system has been developed for the model D-Max [19>] (RG):

- GATEWAY
- DIFFERENTIAL LOCK ELECTRONICS
- PARK ASSIST
- START&STOP
- A/C
- NAVIGATOR

A new diagnostic system has been developed for the model MU-X [21>] (RJ):

- GATEWAY
- DIFFERENTIAL LOCK ELECTRONICS
- PARK ASSIST
- START&STOP
- A/C
- NAVIGATOR

JEEP

A new diagnostic system has been developed for the model Avenger [23>]:

- ABS
- AIRBAG
- GEAR SELECTOR LEVER

JMC

A new diagnostic system has been developed for the model Yusheng S330 [16>]:

- ABS
- GATEWAY
- RADAR
- BODY COMPUTER
- PETROL INJECTION
- TYRE PRESSURE



CAR 76.5.0



- INSTRUMENTATION

KG MOBILITY

A new diagnosis of the SERVICE WARNING LIGHT system has been developed for the models:

- Korando [23>] (C300)
- XLV [23>] (X150)

LAND ROVER

A new diagnosis of the STEERING WHEELS system has been developed for the models:

- Range Rover V [22>] (L460)
- Range Rover Sport III [22>] (L461)

MAZDA

A new diagnostic system has been developed for the model BT-50 [20>] (TF):

- START&STOP
- GATEWAY
- PARK ASSIST
- DIFFERENTIAL LOCK ELECTRONICS
- A/C
- INSTRUMENTATION

A new diagnosis of the GATEWAY system has been developed for the models:

- CX-5 [17>] (KF)
- CX-8 [17>] (KG)

A new diagnosis of the VEHICLE CONNECTION CONTROL UNIT system has been developed for the models:

- CX-3 [17>] (DK) Facelift
- CX-4 [17>] (GK)
- CX-5 [17>] (KF)
- CX-8 [17>] (KG)
- Mazda3 [17>18] (BN)
- Mazda6 [16>] (GL)
- MX-5 [15>] (ND)

MERCEDES-BENZ

A new diagnosis of the HYBRID SYSTEM has been developed for the models:

- A [18>] (177)
- A [18>] (177) Sedan
- B [19>] (247)
- CLA [19>] (118)
- CLA [19>] (118) Shooting Brake
- GLA [20>] (247)



CAR 76.5.0



- GLB [19>] (247)
- GLS [19>] (167)

A new diagnosis of the MULTIFUNCTION CAMERA system has been developed for the models:

- A [18>] (177)
- A [18>] (177) Sedan
- AMG GT [18>] (290) Coupé
- B [19>] (247)
- CLA [19>] (118)
- CLA [19>] (118) Shooting Brake
- GLA [20>] (247)
- GLB [19>] (247)
- GLE [19>] (167)
- GLE [20>] (167) Coupé
- GLS [19>] (167)

A new diagnosis of the SERVICE WARNING LIGHT system has been developed for the models:

- C [21>] (206)
- C [21>] (206) L
- C [21>] (206) T
- E [23>] (214)
- E [23>] (214) L
- E [23>] (214) T
- EQA [21>] (243)
- EQB [21>] (243)
- EQE [22>] (295)
- EQE SUV [23>] (294)
- EQS [21>] (297)
- EQS SUV [22>] (296)
- S [20>] (223)

A new diagnosis of the REAR LEFT MULTI-CONTOUR ORTHOPAEDIC BACKREST system has been developed for the models:

- E [23>] (214)
- E [23>] (214) L
- E [23>] (214) T
- EQE [22>] (295)
- EQE SUV [23>] (294)
- EQS [21>] (297)
- EQS SUV [22>] (296)
- S [20>] (223)

A new diagnosis of the REAR RIGHT MULTI-CONTOUR ORTHOPAEDIC BACKREST system has been developed for the models:

- E [23>] (214)
- E [23>] (214) L
- E [23>] (214) T
- EQE [22>] (295)
- EQE SUV [23>] (294)
- EQS [21>] (297)
- EQS SUV [22>] (296)
- S [20>] (223)

MG

A new diagnostic system has been developed for the model Marvel R [21>] (EP21):

- TRANSMISSION CONTROL MODULE
- HIGH-VOLTAGE BATTERY CHARGE MANAGEMENT
- INTEGRATED STARTER GENERATOR
- BRAKE BOOSTER

A new diagnosis of the PETROL INJECTION system has been developed for the models:

- MG5 [18>] (AP31)
- MG GS [15>19] (AS21)

A new diagnostic system has been developed for the model MG5 [20>] (EP22/AW31) Wagon:

- HIGH-VOLTAGE BATTERY CHARGE MANAGEMENT

A new diagnostic system has been developed for the model MG HS [18>] (AS23):

- HYBRID SYSTEM
- PETROL INJECTION

PEUGEOT

A new diagnostic system has been developed for the model 3008 [16>] (P84):

- SPIA SERVIZIO

ROEWE

A new diagnosis of the PETROL INJECTION system has been developed for the models:

- i5 [18>] (AP31)
- i6 [16>] (IP31/IP34)
- RX5 [16>] (AS22/AS24)
- RX5 Max [19>] (AS28)
- RX8 [18>] (IS21)

A new diagnosis of the HIGH-VOLTAGE BATTERY CHARGE MANAGEMENT has been developed for the models:

- Marvel X [18>] (EP21)
- Ei5 [18>] (EP22/AW31)

A new diagnostic system has been developed for the model Marvel X [18>] (EP21):

- INTEGRATED STARTER GENERATOR

TATA

A new diagnosis of the "INSTRUMENTATION" system has been developed for the models:

- Bolt [14>]
- Tiago [16>]
- Tigor [17>]
- Zest [14>]

VOLKSWAGEN

A new diagnosis of the DIESEL INJECTION system has been developed for the models:

- Amarok [23>] (T1)
- Multivan T7 [22>] (STM)

A new diagnostic system has been developed for the model Multivan T6 [15>19] (SGM):

- TRUNK

SUPERCAR

MERCEDES-BENZ

A new diagnostic system has been developed for the model AMG ONE [22>] (298):

- ABS
- DC/DC CONVERTER
- BATTERY CONTROL MODULE

NOTICE FOR CUSTOMERS WHO OWN A Windows PC

Dear Customers, to make the most of all the functions in the TEXA IDC5 diagnostic software, you need to update your Personal Computers to the latest version of the operating system Windows 10 or Windows 11.

OTHER NOTICES

Please note that the software updates are not available for unsupported tools

For more information, please contact your trusted TEXA dealer.

Please note that this document is confidential. Total or partial copying without authorisation by TEXA S.p.A. is forbidden. Data, descriptions and illustrations may vary with respect to those shown here. TEXA S.p.A. reserves the right to make changes of any kind to its products, without prior notice.